

Thermo / Jouan

422 Series



Motor Rebuild Only
For K422 Series
OEM:25509607
P/N:OCM-09F



Brush Pair
OEM:26160032
P/N:CB-099

4232



Motor Exchange
Rebuild Price Available!
OEM:89000511
P/N:OCM-09R



Brush Pair
OEM:86000637
P/N:CB-133

B412/4235



Motor Exchange
Rebuild Price Available!
OEM:11201499
P/N:OCM-09P



Brush Pair
OEM:86000056
P/N:CB-133

C411/C300



Motor Exchange
Rebuild Price Available!
OEM:25509545
P/N:OCM-09A



Brush Pair
OEM:86000637
P/N:CB-133

C4I



Motor Exchange
Rebuild Price Available!
OEM:89002888
P/N:OCM-09FF

4237



Motor Exchange
Rebuild Price Available!
OEM:11201527
P/N:OCM-09EE

B311 / BR311



Motor Exchange
Rebuild Price Available!
120V B/BR311
OEM:25509608
P/N:OCM-09B



Brush Pair
Before 06/1988 .2515"
OEM:25160027
P/N:CB-063A



Brush Pair
After 06/1988 .2300"
OEM:26160031
P/N:CB-097